DEPARTMENT OF THE ARMY TECHNICAL MANUAL DEPARTMENT OF THE NAVY MANUAL DEPARTMENT OF THE AIR FORCE MANUAL UNITED STATES COAST GUARD MANUAL FEDERAL AVIATION ADMINISTRATION HANDBOOK

TM 11-2557-28 OPNAV INST, 3721.18 AFM 101-3 CG 387 6000.6

UNITED STATES INTERAGENCY GROUND INSPECTION MANUAL

AIR TRAFFIC CONTROL AND NAVIGATIONAL AID FACILITIES



APRIL 1967

DEPARTMENTS OF THE ARMY, THE NAVY, AND THE AIR FORCE
THE UNITED STATES COAST GUARD
AND THE FEDERAL AVIATION ADMINISTRATION



DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION

6000.6 CHG 2

USAF.....AFM 101-3 CHG 2 NAVY.....G: NAVINST 3721.18 CHG 2 ARMY......TM 11-2557-28 C2

29 Jan 73

Cancellation Date: After filing

UNITED STATES INTERAGENCY GROUND INSPECTION MANUAL - AIR TRAFFIC SUBJ: CONTROL AND NAVIGATIONAL AID FACILITIES

- 1. PURPOSE. This Change transmits revised pages to the subject manual to promulgate technical standards associated with implementation of ILS-VOR-TACAN (DME) 50 kHz/Y channels. Also, revised pages are included to make minor editorial corrections.
- 2. DISTRIBUTION. This Change will be distributed to holders/users of the subject manual in selected offices of the Department of Defense. United States Coast Guard and Federal Aviation Administration (see attached distribution list).
- 3. EXPLANATION. Frequency congestion has and will continue to limit the growth of the navigational system in high density areas of the United States. The logical solution to this problem is to provide additional frequencies by implementing 50 kHz VOR and ILS, and associated "Y" TACAN (DME) channels. Preparatory to implementing these channels, new and existing VOR-ILS navigational aids used in the NAS, require improvement to stabilize transmitter carrier frequency from 0.005% to 0.002%. Facility improvements to achieve a carrier frequency stability of 0.002% shall be initiated by 1 January 1973 and completed as soon as possible thereafter but no later than 1 July 1973.

Subsequent to 1 January 1975, as frequency congestion spreads within the Continental United States; VOR ground stations operating in the band 108.0 to 112.0 mHz will require improvement, on a selective basis, to meet the 9960 Hz subcarrier criteria shown below. Facility owners will be given six (6) months notice to make these improvements.

Subcarrier	<u>Level</u>
9960 Hz	0 dB reference
2nd harmonic	-30 dB
3rd harmonic	-50 dB
4th harmonic and above	-60 dB

Distribution: WAF/RD/AT/FS/LG-2; RAF/FS/AT-3; M-1; FNF-0 (Minimum)

Initiated By: AAF-410

Since improvement of carrier frequency stability is National (as opposed to International) in scope, the technical standards supporting this revision to the subject manual are found in Advisory Circular AC 00-31, "U.S. National Aviation Standard for the VORTAC System", dated 10 June 1970 (also known as Order 1010.55, of the same title, dated 1 June 1970).

	PAGE CONT	ROL CHART	
Remove Pages	Dated	Insert Pages	Dated
Foreword Signatures Distribution	1/9/71 1/9/71 April 1967	Foreword Signatures Distribution	29 Jan 73 29 Jan 73 29 Jan 73
Page 5 Page 6 Page 9	1/9/71 1/9/71 April 1967	Page 5 Page 6 Page 9	29 Jan 73 29 Jan 73 29 Jan 73
Page 10 400 Appendix, Page 1 400 Appendix, Page 3	April 1967 1/9/71 April 1967	Page 10 400 Appendix, Page 400 Appendix, Page	29 Jan 73 1 29 Jan 73

William M. Flener Acting Deputy Associate Administrator for Operations

Page 2



DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION

6000.6 CHG 1

1/9/71

Concellation after filing Date:

SUBJ: UNITED STATES INTERAGENCY GROUND INSPECTION MANUAL - AIR TRAFFIC CONTROL AND NAVIGATIONAL AID FACILITIES

- 1. <u>PURPOSE</u>. This change transmits revised pages to the subject manual.
- 2. EXPLANATION. The revised pages eliminate a conflict between the subject manual and agency Order 6000.1A, dated 8 March 1968, entitled "Certification and Operation of Military—Maintained Air Navigation Facilities in the National Air—space System". Upon issuance of this Change, a formal written certificate will be required only once; at the time a facility is accepted for use in the National Airspace System. In addition, other revisions include: the addition of the quadradar system, minor changes in radar performance measurements and a change in ground check error spread tolerance for certain VOR equipment.

PAGE CONTROL CHART

Remove Pages	Dated	Insert Pages '	Dated
Foreword	4/67	Forew ord	1/9/71
Page i	4/67	Page i	1/9/71
Page 3-4	4/67	Page 3-4	1/9/71
Page 5-6	4/67	Page 5-6	1/9/71
Page 27-28	4/67	Page 27-28	1/9/71
Page 33-34	4/67	Page 33-34	1/9/71
400 Appendix,		400 Appendix,	
Page 1-2	4/67	Page 1-2	1/9/71

G. S. MOORE

Associate Administrator for Operations, OP-1

Distribution: WSM/WRD/WAT/WFS/WLG-4 RMAF/FS/AT-3 FAF-0 (1 copy ea.)

Initiated by: SM-121

DEPARTMENT OF THE ARMY TECHNICAL MANUAL
DEPARTMENT OF THE NAVY MANUAL
DEPARTMENT OF THE AIR FORCE MANUAL
UNITED STATES COAST GUARD MANUAL
FEDERAL AVIATION ADMINISTRATION HANDBOOK

TM 11-2557-28 OPNAV INST. 3721.18 AFM 101-3 CG 387 6000.6

UNITED STATES INTERAGENCY GROUND INSPECTION MANUAL AIR TRAFFIC CONTROL AND NAVIGATIONAL AID FACILITIES

FIRST EDITION

DEPARTMENTS OF THE ARMY, THE NAVY, AND THE AIR FORCE
THE UNITED STATES COAST GUARD
AND THE FEDERAL AVIATION ADMINISTRATION

6000.6 CHG 2 January 1973

FOREWORD

The purpose of this manual is to prescribe standardized criteria for interagency use in determining and certifying the technical performance of certain military-maintained air traffic control and navigational aid facilities designated for use in the National Airspace System. Further, the prescribed criteria shall be used in determining the technical performance of all air navigation facilities maintained and operated by a military service when specifically directed by an appropriate regulation, notice, etc. These criteria essentially comprise the technical performance standards and tolerances for application at the various facility types. Guidance regarding those maintenance procedures requiring subsequent flight inspections, and procedures to be followed in ground inspecting and certifying facilities and in issuing Notices to Airmen are also furnished. This manual is not intended as authorization for an agency to assume ground inspection authority over any group of facilities which are not now under its jurisdiction. Similarly, it carries no designation of responsibility within any agency unless such has been so designated in its usual procedural manner, such as general orders, regulations, etc.

This manual is directive upon all personnel charged with the responsibility for the ground inspection of military-maintained air traffic control and navigation aid facilities used in the National Airspace System, when a facility is so designated by its agency. Compliance with this manual, however, is not a substitute for common sense and sound judgment. Nothing in this manual shall be construed to relieve maintenance or supervisory personnel of the responsibility of exercising initiative in the execution of their program, or from taking such emergency action as the situation warrants.

The Federal Aviation Administration will coordinate and provide approved changes to this manual by means of a page revision method. Revised pages will be transmitted by Federal Aviation Administration Change. Recommendations concerning changes or additions to the subject material are welcomed and should be forwarded to one of the following addresses:

Chief of Staff, U.S. Army, Washington, D.C. 20310 Chief of Naval Operations, Navy Department, Washington, D.C. 20350 Chief of Staff, U.S. Air Force, Washington, D.C. 20330 Commandant, U.S. Coast Guard, 400 7th Street, SW., Washington, D.C. 20590 Administrator, Federal Aviation Administration, Washington, D.C. 20591

This manual has been officially approved by: Chief of Staff, U.S. Army; Chief of Naval Operations, U.S. Navy; Chief of Staff, U.S. Air Force; Commandant, U.S. Coast Guard; and the Administrator of the Federal Aviation Administration. The effective date of the manual shall be the date of signature of the last signatory agency.

i,

6000.6 CHG 2 January 1973

BY ORDER OF THE SECRETARIES OF THE ARMY, NAVY, AND AIR FORCE; COMMANDANT OF THE U.S. COAST GUARD; AND THE ADMINISTRATOR OF THE FEDERAL AVIATION ADMINISTRATION

OFFICIAL:

VERNE L. BOWERS, Major General, U.S. Armyr The Adjutant General. CREIGHTON W. ABRAMS, General, United States Army, Chief of Staff.

Official:

T. F. DEDMAN,
Rear Admiral, U.S. Navy,
Assistant Vice Chief of Naval Operations/
Director of Naval Administration.

OFFICIAL:

DWIGHT W. COVELL, Colonel, U.S.A.F., Director of Administrative Services. JOHN D. RYAN, General, United States Air Force, Chief of Staff

OFFICIAL:

FRANK V. HELMER, Rear Admiral, U.S.C.G., Chief, Office of Operations.

Official:

J. W. COCHRAN, Director, Airway Facilities Service, Federal Aciation Administration. GEORGE S. MOORE, Associate Administrator for Operations, Federal Aciation Administration. 6000.6 CHG 2

DISTRIBUTION

U.S. Navy	•	U. S. Navy	Continued
SNDL		FKQ1	Electronic Systems Command Ac-
$\Lambda 4\Lambda$	Chief of Naval Material		tivity
24A	Naval Air Force Commanders	FKQз	Electronic Systems Command Divi-
24.J	Fleet Marine Force Commands		sion
42A	Fleet Air Commands (Less COM- FAIRAZORES, COMFAIR-	FKQ1	Electronic Systems Test and Eval- uation Facility
	MED/COMASWFORSIXTH-	FKR1A	Air Station NAVAIRSYSCOM
	FLT, COMFAIRWESTPAC,	FR3	Air Station CNAVRES
	COMFAIRWESTPAC DET MISAWA, COMFAIRWEST-	FR4	Air Facility CNAVRES
	PAC DET CUBI PT)	FT1	Chief of Naval Training
C2	Naval Officers at Air Force Activi-	FT2	Chief of Naval Air Training
C4F8	ties (NAVREPS only)	FT5	Chief of Naval Air Technical Train- ing
C. 11 11	Annexes, Branches, Groups, Ranges and Auxiliary Landing Fields	FT6	Air Station CNT
	(NALF Crows Landing, NALF San Clemente Island only)	FT13	Air Technical Training Center (NATTC Glynco only)
FF4	Air Facility CNO (NAF Wash)	V5	Marine Corps Air Station
FA6	Air Station LANT	OP'S81/5	
FA7	Station LANT (NAVSTA Argen-), 52(2), 55, 59, 094(2) only
	tia, NAVSTA Guantanamo Bay,	Stocked:	•
	NAVSTA Key West, NAVSTA	COMNA	DIST WASH
	Keflavik, NAVSTA Mayport,	(Supply a	and Fiscal Department—Code 514.3)
	NAVSTA Roosevelt Roads only)	Washingto	on Navy Yard on, D.C. 20390
FB6	Air Facility PAC (NAF El Centro only)		n, D.C. 2039()
FB7	Air Station PAC	U.S. Army:	-
FB10	Station PAC (NAVSTA Adak, NAVSTA Guam, NAVSTA Mid-		nce with AR 95-14
	way, NAVSTA Subic Bay only)	U.S. Air Forc	e:
FD2	Naval Oceanographic Office	Distribution	on F
FKA1A	Air Systems Command Headquarters (5)	Federal Avia	tion Administration:
FKA1B	Electronic Systems Command Head-		/AT/FS/LG—2
	quarters (5)	RAF/FS/	AT_3
FKA6B1	Air Facility CNM	FAF-O (n	
		•	•

6000.6 CHG 1

UNITED STATES INTERAGENCY GROUND INSPECTION MANUAL

AIR TRAFFIC CONTROL AND NAVIGATIONAL AID FACILITIES

TABLE OF CONTENTS

100 General

Section	Page
101 Introduction	1
102 Reserved	1
103 Reserved	1
104 Reserved	1
200 Technical Performance Standards and Tolerances	
201 VHF Omnidirectional Radio Range (VOR/TVOR)	5
202 Instrument Landing System (ILS)	9
203 Tactical Air Navigation System (TACAN)	13
204 Low/Medium Frequency Radio Range (LFR)	17
205 Non-Directional Radio Beacon (NDB)	21
206 Marker Beacons, 75 MHz	23
207–209 Reserved	
210 Radar Facilities	25
211-220 Reserved	
221 Enroute and Terminal Area Communications	29
222 Direction Finding Stations	31
223-230 Reserved	
300 Facility Ground Inspection and Notice to Airmen Procedu	res
301 Facility Ground Inspection and Certification Procedures	33
302 Notice to Airmen Procedures	34
400 Appendix	
401 Glossary and Definitions	1
402 Formal Certificate Form	2 *
403 FAA Regional Offices and Addresses	3

6000.6 April 1967

Page 1 (and 2)

UNITED STATES INTERAGENCY GROUND INSPECTION MANUAL

AIR TRAFFIC CONTROL AND NAVIGATIONAL AID FACILITIES

100 General

101 Introduction

The phenomenal growth of air traffic operations has caused the establishment of a complex system of air traffic control and navigation facilities to enable large numbers of aircraft to move efficiently and safely to their destinations. This system includes FAA, military, and privately owned (non-federal) facilities. Safety of flight and effective control of aircraft movements necessitate that the components of this system be accurate and reliable. Facilities are flight inspected in accordance with criteria in the United

States Standard Flight Inspection Manual, OA P 8200.1. A dynamic maintenance program coupled with recurring ground inspections of air traffic control and navigational aid facilities by trained technical personnel in accordance with appropriate technical performance standards and tolerances will assure the continued accuracy and reliability of the system. In addition, such a program will minimize flight inspection requirements.

102 Reserved

103 Reserved

104 Reserved

Per. 100

6000.6 CHG 1 1/9/71

Pose 5

200 Technical Performance Standards and Tolerances

200.1 Introduction

The technical performance standards and tolerances prescribed by this manual set forth the minimum acceptable performance which a facility * must meet to be certificated for use, or used, in the National Airspace System. Further, when specifically directed by an appropriate regulation, notice, etc., the prescribed performance standards and tolerances of this manual shall be utilized in determining the technical performance of all air navigation facilities maintained and operated by a military service. An appropriate Notice to Airmen shall be issued on any facility later found not to be performing within these standards and tolerances. Pending correction and recertification, the facility shall not be used in the National Airspace System. Facilities * may be maintained in accordance with established maintenance procedures, applicable technical orders, instruction books, and/or other directives so long as performance meets the standards and tolerances prescribed herein.

200.2 Definitions

Definitions of standard, initial tolerance and operating tolerance for the purpose of this hand-book are as follows:

- a. Standard: The optimum value assigned to an essential parameter of the equipment or system to obtain normal operating performance.
- b. Initial Tolerance: The maximum deviation, from the standard value of the parameter, which is permissible at the time of initial tune-up or a major readjustment.
- c. Operating Tolerance: The maximum deviation, from the standard value of the parameter, beyond which remedial action is mandatory.

200.3 Explanation of Terminology

Each essential equipment parameter has been assigned a standard value, which, by definition, is

the optimum value which will provide normal operating performance. These standard values are compatible with the design capability of the equipment involved, and, from a systems engineering viewpoint, with normal operation of the overall system of which it is a part.

In addition, each essential equipment parameter has been assigned an "initial" and an "operating" tolerance expressed in terms of the permissible deviation from the "standard" value, or in absolute maximum and/or minimum performance levels, as appropriate.

The initial tolerances are those limits within which an equipment must operate in order to be certificated and accepted for use in the National Airspace System at the time of initial commissioning or after a major overhaul, modification or modernization.

The operating tolerances are those limits which are acceptable in terms of meeting system requirements, and within which an equipment may continue to operate on a certified basis without adjustment or corrective maintenance.

200.4 Modifications

Army, Navy, Air Force, or Coast Guard equipment or facilities may be modified or altered only in accordance with current directives issued by the cognizant agency. In addition, any modification or alteration which will affect the certificated operating performance of any military-maintained equipment or facility that has been designated for use in the National Airspace System must be coordinated with the Washington Headquarters, FAA for concurrence prior to the modification being made, except as follows:

(1) The above requirement for coordination shall not be construed to inhibit the accomplishment of normal equipment maintenance and repair which shall be coordinated in accordance with the Notice to Airmen Procedures contained in paragraph 302.

Por. 200

Page 4

6000.6 CHG 1 1/9/71

- (2) It is recognized also that there will be occasions when certain temporary alterations or modifications will be necessary due to an emergency situation, or for the development or test of equipment or system improvements. In these cases, coordination shall be accomplished as follows:
- (a) Any necessary alteration or modification required in an emergency situation may be coordinated directly with the designated FAA Maintenance Liaison Officer (MLO) responsible for the affected facility. Equipment affected by these changes will be returned to its original configuration at the earliest practica ldate.
- (b) The temporary alteration or modification of a single equipment for test purposes or to determine the feasibility of a proposed improvement may be coordinated directly with the cognizant FAA Regional authority. The test period should be limited to that time required to obtain sufficient data for a fully documented analysis. After completion of the test, the equipment will be returned to its original configuration, or a fully documented request for approval as a permanent modification shall be submitted to the cognizant Military Headquarters for coordination with Washington Headquarters, FAA as required above.

Par 200.4

201 VHF Omnidirectional Radio Range (VOR/TVOR)

201.1 Description

VOR (Very High Frequency ()mnidirectional Range) operates in the 108 to 118 MHz band. It provides omnidirectional azimuth information to an aircraft for short range enroute air navigation. Identification is provided by a keyed I,020 Hz tone, supplemented at some stations by voice recording. Voice

may be provided for communications from ground to air. Monitoring is provided for course alignment and signal output from the station by means of detector units mounted external to the radiation system.

201.2 Tabulation of Standards and Tolerances

	201.2	201.2 Tabulation of Standards and Tolerances			
		Item	Standard	Initial Tolerance/Limits	Operating Tolerance/Limits
	(1) Fr	(1) Frequency Tolerances: (a) Transmitter frequency (b) V()R Goniometer Supply Fre.	Assigned Frequency	+0.002%1	Same as initial. Do.
		quency. (c) Frequency of 1,020 Hz Oscillator	upon equipment design).	±25 1fz	±50 IIz.
		(d) Audio Response Requirements for Voice Frequencies.	Flut between 300 and 2,000 Hz.	The sine-wave audio response characteristics	Same as initial.
		er ver		of the system with ref- erence to the frequency	
	,			of maximum response shall be within 6 dB	
				between 300 Hz and 2,000 Hz.	
	(2) M	(2) Modulation Levels:	200 00	8.8 0.9	% ? ? ?
		(b) Variable Signal Modulation	30%	20 to 31%	28 to 32%.
		(c) Code Identification (1,020-Hz)	8%	7 to 9%	6 to 10%.
7		(d) Voice Identification (400-Hz sine	28%	27 to 29%	26 to 30%.

*Initial tolerance/limits changed from ±0.005% to ±0.002%. Effective date of ±0.002% tolerance is 1 July 1973.

Pege	6

		3	77	fiem Item		H* sine	Standard 98%	Initial Tolerance/Limits	Operating Tolerance/Limits 26 to 30%.
201.2			waw waw Residu the	(f) Residual Amplitude Modulation in 0the Modulation.	e Modu Elimina	lation in tor.	0	Less than 5%	Less than 5%.
	(3)	Monitc (*)	or Systei) Cours	(3) Monitor System Tolerances: (a) Course Shift (phase alarm)	: e slarm)	1	The monitor shall alarm for course shifts in ex-	Same as standard	Same as standard.
		එම) Refer	(b) Reference Level Alarm Tolerances -(c) Variable Level Alarm Tolerances	arm To! rm Tole	erances -	cess of ±1 degree. 13% decrease	12 to 14% decrease	11 to 15% decrease. 11 to 15% decrease.
•	æ '	Gound (a	(4) Gound Check: (a) The facility // Moni	.2 Z Q	meet tl muth in sk error	ne followin dication ta curves slm	ng ground check tolerances ken within a 15-minute pe ill not deviate from the ref	ck: o facility must meet the following ground check tolerances when recertification is by ground check: 1. Monitor azimuth indication taken within a 15-minute period shall not vary more than 0.3 degree. 2. Ground check error curves shall not deviate from the reference ground check error curve in excess of 1 degree.	ground check: lian 0.3 degree. surve in excess of 1 degree.
				The refer	ence gro	und check	error curve is the average	The reference ground check error curve is the average of three successive error curves taken influentiately to	IVES lakell illinearage in

lowing a basic altitude flight inspection, not varying more than 0.3 degree from each other.

3. The maximum error spread of any ground check error curve shall not exceed 2 degrees.

4. The ground check error curves for dual transmitter facilities shall not deviate from each other by more than 1

(b) The facility must meet the ground check tolerances indicated above when recertification is by flight inspection, with the following exceptions:

The ground check error curves for dual transmitter facilities shall not deviate from each other by more than 1.5 1. The maximum error spread of any ground check error curve shall not exceed 4 degrees.

• (5) Subcarrier Harmonics: the sideband level of the harmonics of the 9,96? Hz component in the radiated signal shall not exceed the following levels referred to the level of the 9,960 Hz fundamental sideband

Odl3 reference 2nd Harmonic -30 dB 3rd Harmonic -50 dB Harmonic -60 dB 4th and above

*Subsequent to 1 January 1975, as frequency congestion spreads within the CONUS, VOR ground stations operating within the band 108-112 mHs will require improvement on a selective basis to meet the 9900 Hz subsarrier criteria shown herein. Facility owners will be given six months The maximum error spread of any ground check error curve for the Wilcox, La Voie, Colling, Lorenz, and Mobile systems shall not exceed three

notice to make these improvements.

; ;

6000.6 April 1967 Page 7 (and 2)

201.3 Flight Inspection Requirements

201.31 A flight inspection will be required if a VOR facility does not meet the ground check tolerances outlined in Section 201.2(4)(a) after the following maintenance activities are performed:

- (1) Replace or reposition any fixed field detector, or replace or modify any evaluating element in the VOR monitor system if the signal level or course indication was abnormal immediately before and immediately after this work was accomplished.
- (2) Repair or replace goniometer.
- (3) Adjust or replace any of the following:(a) RF transmission lines, including feed

lines, stubs, positioners, bridges; (b) antennas and components, including pedestals, loops, baluns, supporting braces.

201.32 A flight inspection will be required, regardless of ground check results, after the following maintenance activities are performed:

- Perform imodernization or corrective maintenance of a major nature such as modification of the counterpoise.
- (2) Following new construction in the vicinity such as sheds, hangars, water tanks, fences, grading, utility lines, etc, which may create conditions not detectable by ground observation.
- (3) Change operating frequency of facility.

Per. 201.3

202 Instrument Landing System (ILS)

Description 202.1

instrument landing system is designed to provide an on final approach to a runway. The system usually consists of approach path for exact alignment and descent of an aircraft tors and various lighting systems. The standards set forth a localizer, glide slope and one or more markers, compass locaherein cover the localizer and glide slope only. Markers and compass locator standards are given under the 75 MHz Marker Equipment and Low Frequency Homing Bearon sections respectively. The

Localizer—Lxvulizer facilities radiate field patterns of 90. and runway to provide a course for guidance in the horizontal plane. 150-Hz modulated energy on opposite sides of the instrument The 90-Hz energy predominates to the left side of an aircraft on final approach when the aircraft is "on course

Clide Stope-Glide slope facilities radiate field patterns of 90. and 150-Hz modulated energy to provide a path for Ruidance in the vertical plane. The 90-11z energy predominates alkove an aircraft on final approach when the aircraft is on the correct glide path angle.

202.2 Tabulation of Standards and Tolerances

calizer
Poca
_
2.7

#(1) BF Frequency
(a) 90 Hz and 150 Hz (b) 1,020 Hz (if applicable)
I. Standard Localizer Trans. 45% reduction
8. Waveguide Clearance Array 20% reduction
3. Waveguide Array Traus. 20% reduction
(b) Course Shift Alarm
(c) Course Width Alarm (percent of es. 15%tablished width).

Where two radio frequency carriers are used, the initial tolerance shall not exceed ±0.001% and the operating tolerance rhull not exceed Initial tolerance/limits changed from ±0.003% to ±0.002% and operat- $\pm 0.002\%$ with the frequencies symmetrical about the assigned frequency.

1

ing tolerance/limits from ±0.005% to same as initial. Effective date of new tolerance/limits is 1 July 1973.

² Except when designated otherwise by the Flight Inspector for specific facility.

Page	10	
Janua	γ	1973

Item	Blandard	Initial Tolerance/Limits	Operating Tolerance/Limits
(1) RF Frequency	Assigned frequency	±0.002%	Same As Initial. *
(2) Power Output	Rated output	80% of std., min	75% of std., min.
(3) Modulation:			
	80%	79 to 81%	78 to 82%.
(b) 150 Hz trough	80%	79 to 81%	78 to 82%.
(c) 90/150 Hz equality	Equal	±0.5%	±1%.
(4) Monitor:			
(a) Power Reduction Alarm	45 reduction	43 to 47% reduction	40 to 50% reduction.
(b) Path Shift Alarm'	±0.2°	±0.2°	±0.2°.
(c) Path Width Alarm	+0.9°	±0.2°	±0.2°.

*Initial tolerance/limits changed from ±0.003% to ±0.002% and operating tolerance/limits from ±0.005% to same as initial. Effective date of osw tolerance/limits is 1 July 1873.

*Except that, at facilities whose operating path angle is less than 2.07, the tolerance shall be 0.075 times the angle.

Per. 202.22

6000.6 April 1967 one 11 land 121

202.3 Flight Inspection Requirements

202.31 Localizer

A flight inspection will be required when any of the following conditions exist:

- (1) Major changes in local airport obstructions, buildings, etc., which may affect the radiated localizer course or clearance structure.
- (2) When airport construction, runway repairs, etc., are being performed in the general localizer area without a facility shutdown and any doubt of facility reliability exists.
- (3) Critical component modification or replacement, including transmitters as units, bridges, motor alternators, phasers, transmission line and antennas.
 - (4) Antenna, repair and repositioning.
- (5) Removal of equipment to accomplish site check and reinstallation of that set of equipment.

202.32 Glide Slope

A flight inspection will be required when any of the following conditions exist:

- (1) Major changes in local airport obstructions, buildings, etc., which may affect the radiated glide slope path structure.
- (2) When airport construction, runway repairs, etc., are being performed in the general glide slope run without a facility shutdown and any doubt of facility reliability exists.
- (3) Critical component modification or replacement, including transmitters as units, bridges, modulator troughs or parts, power dividers, phasers, transmission line and antennas.
 - (4) Antenna servicing, repair and repositioning.
- (5) Changes in modulator unit adjustments (other than those required to accomplish maintenance routines, followed by return to pre-existing conditions).
- (6) Removal of equipment to accomplish site check and reinstallation of that set of equipment.

3 3

4000.6 April 1967

203 TACAN (Tactical Air Navigation) System

203.1 Description

The TACAN system provides omnidirectional azimuth and distance information to an aircraft for short runge remote enroute air navigation. It has the capability of being used as an instrument letdown and approach aid. TACAN ground equipment consists of either a fixed or mobile transmitting unit. The airborne unit

in conjunction with the ground unit reduces the transmitted signals to a visual presentation of both azimuth and distance information. TACAN is a pulse system and operates in the UHF band of frequencies from 960 to 1215 MHz.

203.2 Tabulation of Standards and Tolerances

(2) North Burst Pulse Count (Pulses 1,800. (2) North Burst Pulse Pairs. (3) North Burst Pulse Pairs. (4) Auxiliary Burst Pulse Pairs. (5) Auxiliary Burst Pulse Pairs. (6) Auxiliary Burst Pulse Pairs. (7) Auxiliary Burst Pulse Pairs. (8) Identification Tone (Continuous) and 6,660 pps. (9) Identification Tone (Continuous) and 6,660 pps. (9) Beacon Receiver Selectivity: (9) Beacon Receiver Decoder Acceptance at ±100 kHz. (9) Beacon Receiver Decoder Acceptance Spacing varied from 12.5 pase. (10) Beacon Receiver Pulse Pairs. (11) 120 pase. (2) North Burst Pulse Duration (1st to 11th 120 pase.) (3) Beacon Receiver Selectivity: (4) Auxiliary Burst Pulse Pairs. (5) Auxiliary Burst Pulse Pairs. (6) Identification Tone (Continuous) and 6,660 pps. (7) Beacon Receiver Selectivity: (8) Beacon Receiver Selectivity: (9) Beacon Receiver Decoder Acceptance Spacing varied from 12.5 pase. (9) Beacon Receiver Pulse Pairs. (10) Do. (11.5 thru 12.5 pase.) (12.5 pase. (12.5 pase. (13.0 pase. (14.10 pase. (15.10 pase. (16.10 pase. (17.10 pase. (18.10 pase. (19.10 pase. (10 pas		. Item	Standard	Initial Tolerance/Limite	Operating Tolerance/Limits
Lbo	Ξ	Reference Burst Pulse Count (Pulses	1,800	Same as standard	Same as standard.
± 5 μsec		per Second).			i
Same as standard	3	North Burst Pulse Pairs	12 pr	Do	Do.
Same as standard	ල	North Burst Pulse Duration (1st to	330 µsес	± 5 µsec	± 10 µsec.
Same as standard		23rd Pulse).		,	•
ity as Receiver sensitivity within 3 dB of on-frequency sensitivity. Not more than 25 replies to 400 off-frequency interrogations at -30 dBm. No more than 0.5 dB clange in receiver sensitivity as pulse spacing varied 11.5 thru 12.5 µsec.	₹	Auxiliary Burst Pulse Pairs	6 pr	Same as standard	Same us standard.
ity as Receiver sensitivity within 3 dB of on-frequency sensitivity. In 3 dB of on-frequency sensitivity. Not more than 25 replies to 400 off-frequency interrogations at -30 dBm. No more than 0.5 dB clange in receiver sensitivity as pulse spacing varied 11.5 thru 12.5 µsec.	9	Auxiliary Burst Duration (1st to 11th Pulse).	120 µsес	±1 µsec	±2 µsec.
ity as Receiver sensitivity within 3 dB of on-frequency sensitivity. Iency Not more than 25 replies to 400 off-frequency interrogations at -30 dBm. No more than 0.5 dB clange in receiver sensitivity as pulse spacing varied 11.5 thru 12.5 µsec.	(9)	Identification Tone (Continuous) and Burst Pulse Count.	6,660 pps	Same as standard	Same us standard.
ity as Receiver sensitivity within 3 dB of on-frequency sensitivity. Iency Not more than 25 replies to 400 off-frequency interrogations at -30 dBm. No more than 0.5 dB change in receiver sensitivity as pulse spacing varied 11.5 thru 12.5 µsec.	E @	Beacon Receiver Sensitivity 1	95 dBm min	Do	Do.
interrogations. Decoder Acceptance No replies to off-frequency interrogations. Decoder Acceptance No change in receiver Sensitivity as interrogation Sensitivity as pulse spaction spacing varied from ing varied 11.5 thru 12.5 µsec.		a. Acceptance at ±160 kHz.	Same receiver sensitivity as when on frequency.	Receiver sensitivity within 3 dB of on-frequency sensitivity.	Same as initial.
r Decoder Acceptance No change in receiver sensitivity as interroga-change in receiver tion spacing varied from sensitivity as pulse spaction 11.5 thru 12.5 µsec.	i singletti	b. Rejection at ±900 kHz	No replies to off-frequency interrogations.	Not more than 25 replies to 400 off-frequency interrogations at -30 dBm.	Do.
	9	Beacon Receiver Decoder Acceptance Spacing.	ž	No more than 0.5 dB change in receiver sensitivity as pulse spacing varied 11.5 thru 12.5 µsec.	No more than 1 dB chang in receiver sensitivity a pulse spacing varied 11.5 thru 12.5 µsec.

* 'Minimum effective triggering level at the facility antenna that will provide 60% replice. Equivalent receiver triggering level is function of cable

losses, antenna gain, etc.; and wast be established for each type facility configuration.

Operating Tolerance/Limits Same as standard.	. ±1 μsec. Same as standard.	Same as initial. Same as standard.	Same as initial. ±90 pulse pairs per	second. 52 dB min. 55 dB min.	3.5 kW min. Same as standard.	Max. decrease of 3 dB.	Do. 2 to 2½ min.	⁴ Those equipments which are designed for operation at less than these power levels may be certified at the lower power levels contingent upon meeting all coverage requirements as verified by flight inspection. ⁴ Alarm at 8 dB decrease from standard beacon peak power output at those facilities employing MX-1627 or MX-2229 monitors until monitors are modified or replaced. ⁷ Not applicable at those facilities employing MX-1627 or MX-2229 monitors.
Initial Tolerance/Limits Same as Standard	±1 μsecSume as standard	±0.25 µsecSame as standard	±0.5 μsec ±30 pulse pairs per	second. Same as standarddo.	က်လ	Max. decrease of 3 dB	Do. 2½ min.	 Those equipments which are designed for operation at less the power levels may be certified at the lower power levels conting meeting all coverage requirements as verified by flight inspection. Alarm at 8 dB decrease from standard bencon peak power those facilities employing MX-1627 or MX-2229 monitors until are modified or replaced. Not applicable at those facilities employing MX-1627 or I monitors.
(10) Receiver Sensitivity Monitor Alarm -89 dBm	sply Delay Alarm at 49 µsec and 51	JarmAl	3. ant. 2,	± 0.8 MHz	Output	rror Alarm:	or)	ring level at the facility antenna that will lent receiver triggering level is function of possible facility in and must be established for each type facility in dBm at those facilities employing MX-1627 onliters are medified or replaced. However at those facilities employing MX-1627 and somitors are medified or replaced. The face at those facilities employing MX-1627 or multions are medified or replaced.
(10) Receiver	(11) B (12) M	(13) Beacon Pulse Spacing (14) Monitor Pulse Spacing A	(15) Beacon Pulse Width (16) Beacon Squitter Con	(17) Beacon Spectrum @	(18) Beacon Peak Power (19) Monitor Peak Powe	(20) Monitor A (21) Monitor A 15 Hz	135 Hz (fine err (22) Monitor Identity (O	* Minimum effective trigged provide 60% replies. Equiva cable losses, antenna gain, etc.; configuration. Alarm at -83 or MX-2259 monitors until m - * Alarm at 45 sace and 55 or MX-2229 monitors "nutil m - * Alarm at 9 sace and 15 sac. * * Alarm at 9 sace and 15 sac. * * * * * * * * * * * * * * * * * * *

6000.6 April 1967

Page 15 (and 16)

203.3 Flight Inspection Requirements

203.31 A flight inspection will be required upon any change in the ground equipment or ground environment which cannot be adequately ground checked for its effect on facility accuracy, continuity and reliability. The flight inspection may be abbreviated at the discretion of the Flight Inspection Specialist to include only pertinent features of the commissioning flight check.

Examples of changes that will require a flight inspection are as follows:

(a) Changes in ground equipment:

(1) Antenna replacement or major antenna repair (such as replacement of an antenna central array and/or modulating cylinder).

(2) Frequency (channel) change.

(3) Replacement of beacon and/or monitoring equipment.

(4) Relocation of antenna.

(b) Changes in ground environment:

- (1) Nearby construction which may affect operation.
- (2) Significant changes in vegetation growth near a facility.

75% of std., min.

90% of std., min.

Assigned power.....

204 Low/Medium Frequency Radio Range (L/MFR)

204.1 Description

The L/MFR is a transmitting station which radiates directional operating in the 200 to 415 kIIz frequency band, the L/MFR produces four courses which project radially from the station like spokes radiating two interlocking figure-eight field putterns. Within limits, these courses can be adjusted to furnish any desired radio beams to provide directional guidance for aircraft. It may also be used as an aid for low approach to the airport. Normally from the hub of a wheel. The L/MFR produces these courses by

indication when an aircraft passes over the station. Performance standards and tolerances for the Z marker are given under the alignment, however, the field pattern is such that the courses are not completely independent of one another. The realignment Normally, a 75 MHz station location marker called the Z marker of one course affects the alignment of the other three courses. is also installed at radio range stations to give a visual and aural 75 MHz Marker Equipment Section (206)

204.2 Tabulation of Standards and Tolerances			: :
Ilem	Mandard	Initial Tolerance/Limits	Operating I oterance/Limits
(1) Frequency and Modulation Tolerances:			;
(a) Transmitter Frequency	Assigned frequency	±0.01%	±0.01%.
(b) Crystal Frequency difference at simul-	1,020 IIz	±20 Hz @ low end of	±25 Hz @ low end of
taneous type facilities.		bund.	band.
		±55 Hz @ high end of	±60 Hz @ high end of
		band.	band.
(c) Audio Response Requirements, 250 0 dB	0 dB.	4 dB	6 dB.
to 2,500 Hz, after equilization;			
(withip).			!
(d) Nonsimultaneous Course Informa- 1,020 Hz.	1,020 Hz.	±20 Hz	±25 Hz.
tion Modulating Frequency (Hz).			
(e) Nonsimultaneous Course Information	95%	90 to 100%	90 to 100%.
Modulation.			
(f) Nonsimultaneous Range Voice Mod- 90%	%06	85 to 95%	85 to 95%.
ulation,			
(g) Simultaneous Range Space Modulu- 30%	30%	28 to 32%	2s to 32%.
tion.			
(h) Simultaneous Range Voice Modula- 55%	55%	52 to 58%	50 to 60%.
tion.		•	

Transmitter:

3

As measured with input supply voltage adjusted to specified equipment input voltage.

(a) Power Output 1......

	nce, comus			i
Overaling Toloresis :	40 to 6007	± 1.5 degrees.	- In decrease	100
Initial Tolerance/Limits	45 to 55%	±1 degree	Same as standard	
Standard	50%	0 degrees	±1 degree	
(3) Monitor (if installed):	(a) Alarm Occurs with Range Power re- 50%	(4) Course Alignment and Ground Check Points: (a) Course Alignment by Ground Check. 0 degrees. Maximum deviation from pub-	(b) Maximum variation of actual course ±1 degree	compared to flight inspection data when plotted on a chart.
Per. 20	4.2			

6000.6 April 1967

204.3 Flight Inspection Requirements

204.31 A flight inspection will be required if an L/MFR facility does not meet the initial ground check tolerances outlined in Section 204.2(4) after the following maintenance procedures are performed:

- Retune phone antenna at nonsimultaneous loop range facilities and retune center towers at Adcock tower facilities.
- (2) Make minor retuning adjustments to antenna tuning house secondaries to correct for normal changes in reflected impedance.
- (3) Perform tests which require temporarily moving (and then resetting) the goniometer dial or tuning control to settings other than their normal operating positions.

(4) Replace course shifting resistors in the coupling unit.

(5) Make changes in tower spark-gap settings. (The antenna tuning house transformer secondaries should always be retuned after making this adjustment.)

- (6) Install or remove structures from the range plot.
 - (7) Adjust keyer or link circuit relay.
- (8) Adjust SRA and SMRL space modulation (carrier to sideband current ratios).
 - (9) Retune goniometer circuits.
- (10) Make adjustments to coupling unit pickup of the automatic range monitor.
- (11) Make corrective adjustments to the carrier down lead at SMRL facilities.
- 204.32 A flight inspection will be required, regardless of ground check results, after the following maintenance activities are performed:
 - (1) Repair artificial lines.
- (2) Retune the primary circuits of towers, except center towers.
 - (3) Repair or replace transmission lines.
- (4) Make major repairs or alterations to counterpoise, ground radial systems or antenna.
- (5) Repair or replace any coil or capacitor in the primary circuits of a tower tuning house.

nominal modulation. In these cases initial and operating tolerances shall be adjusted proportional to nominal levels.

205 Nondirectional Radio Beacon (NDB)

205.1 Description

The NDB transmits nondirectional signals whereby the pilot of an aircraft equipped with a loop antenna can determine his bearing and "home" on the station. These facilities normally operate in the frequency band of 200 to 415 kHz, however, fre-

quencies may be assigned up to 1800 kHz. They transmit a continuous carrier with 1020 Hz modulation keyed to provide identification except during voice transmission.

•
~
-
2
•
=
_
7
ž
5
-3
2
ā
•
Ž
8
꽃.
S
4
•
_
7
≒
_ >
ھ
0
<u> </u>
-
어
~
205.
\simeq
- 24

	XCOX Idenication of Managras and Tolerances			
	Item	Standard	Initial Tolerance/Limits	Operating Tolerance/Limits
	(1) Transmitter Carrier Frequency(2) Identification Oscillator Frequency	Assigned frequency	± 0.01%	Same as initial. Do.
	(3) Modulation Levels:	•		
	(a) NDB Nonsimultaneous (except HH			
	Facilities):			
	Voice	70%	65 to 70%	Do.
	Tone	70%	65 to 70%	Do.
	(b) HH Facilities: '			
	Voice	40%-	38 to 42%	35 to 45%.
	Tone	40%	38 to 42%	35 to 45%.
	(c) NDB Simultaneous (Includes Com-			
	pass Locators LMM, LOM):			
	Voice	70%	68 to 72%	65 to 75%.
	Tone	20%	17 to 21%	15 to 22%.
	(d) Converted L/MF Range (H Facility):			
	Voice	60%	58 to 62%	55 to 65%.
	Tone	20%	17 to 21%	15 to 22%.
	(4) Monitoring (RF Alarm Level)	50% power reduction	50% power reduction	60% power reduction.
	(5) Output Power Ratings:			
	(a) Class HH 12,000 watis or over	As required to meet the	±10%	± 10%.
		specified coverage as determined by Flight		
		Inspection.		!
	(b) Class H, MLOM 50 to 2,000 watts	Same as (5)(a) above	±10%	±10%.
	(c) Class MH, MLOM 25 to 50 watts	Same as (5)(a) above	±10%	±10%.
	(d) Compass Locators (LMM, LOM).	Same as (5)(a) above	±10%	± 10%.
h	Not more than 25 water.			

Due to various types of transmitter installations at specific locations modulation levels may be adjusted either as low as 30% or as high as 85%

Page 22

6000.6 April 1947

205.3 Flight Inspection Requirements

205.31 A flight inspection will be required after the accomplishment of any of the following:

- (1) Change in the output level for the purpose of increasing or decreasing its service area.
- (2) Changes in the antenna or transmitter which may affect facility coverage.

Par. 205,3

6000.6 April 1967

١

206 Marker Beacon (75 MHz)

206.1 Description

A marker beacon serves to identify a particular location in space along an airway or on the approach to an instrument runway. This is done by means of a 75 MHz transmitter which transmits a directional signal to be received by aircraft flying overhead. These stations, commonly called markers, are generally used in conjunction with Low Frequency Radio Ranges and

the Instrument Landing System as point designators. Four classes of markers are now in general use: the class FM, the class LFM, the station location or Z-Markers, and the ILS marker beacons. All four classes use crystal controlled transmitters. The transmitted signal is directed unward by means of a directional antenna array with a counterpoise beneath.

Tolerances
껕
Š
-8
후
š
ਲੱ
7
용
-
엇
8
ă

	Item	Standard	Initial Tolerance/Limits	Operating Tolerance/Limits
Ξ	(1) Carrier Frequency	75 MHz	±0.01%	±0.01%.
2	() Modulation Level	100%	97 to 100%	95 to 100%.
9	(3) Monitor Transfer	25% reduction in power	25% reduction in power	20 to 30% reduction in
		or modulation.	or modulation.	power or modulation.
₹	Modulation Frequencies:			
•	(a) FM and LFM	3,000 Hz	±15 Hz	±30 Hz
	(b) Z Markers	3,000 Hz	±15 Hz	±30 Hz
	(c) ILS Outer Marker	400 Hz	±1 Hz	±4 Hz
	(d) ILS Middle Marker	1,300 Hz	±3 Hz	±13 Hz
	(e) ILS Inner Marker	3,000 Hz	±8 Hz	±30 Hz
	(f) ILS Localizer Back Course	3,000 Hz	±8 Hz	±30 Hz
	Markers.			

Per. 20

Page 24

6000.6 April 1947

206.3 Flight Inspection Requirements

206.31 A flight inspection will be required after the accomplishment of the following maintenance procedures:

(1) Any changes or adjustments to transmitter equipment, transmission lines and/or antenna aray which may affect the radiated pattern in terms of its shape or coverage.

Per. 204.3

6000.6 April 1967

210 Radar Facilities

210.1 Introduction

A Radar Facility, as used here, includes any system, any part of any system, or any ancillary equipment that is used by the FAA Air Traffic Service in the National Airspace System. It will include enroute, terminal, precision, and secondary radar systems such as long/medium range surveillance radars exemplified by the AN/FPS-8, AN/FPS-20A, AN/FPS-37, ARSR-2, etc.; airport surveillance and precision approach radars exemplified by the AN/FPN-28, AN/MPN-5, AN/CPN-4, ASR-5 (AN/FPN-47), PAR-2, AN/MPN-11, etc.; and secondary surveillance radar exemplified by AN/GPX-8, AN/UPX-1. AN/GPX-9B, ATCBI-1, etc.

210.2 Definition

The composition of each Radar Facility will be defined for each individual case by listing exactly the affected equipments and/or components in the local interagency agreement which accomplishes the fact of FAA use. Such a local agreement will be part of the record at the Radar Facility as well as at the using facility (an FAA Air Route Traffic Control Center, for example). Thus, both the users and the maintainers of any Radar Facility will use a specific, exact, and common definition.

210.3 General Requirement

Any radar system that is the property of and is maintained by the Department of Defense or United States Coast Guard and that is to be used by the FAA in the National Airspace System, must be flight inspected in accordance with Par. 104.2 of the United States Standard Flight Inspection Manual (USSFIM), FAA OA P 8200.1. Army TM 11-2557-25, Navy NAVWEPS 16-1-520, USAF AFM 55-8, USCG CG-317. In complying with the requirements of Par. 106.21(2) of the USSFIM, the particular radar system to be flight inspected will have been tuned, calibrated, adjusted, and all measurements taken to insure that the radar is operating in accordance

with the applicable technical orders, manuals, and any applicable interagency agreements. A record of such actions and measurements will have been made. This record will be the basis for the daily and quarterly certification that the facility meets performance and operational requirements as in Par. 301 and 301.2 of this manual.

210.4 USAF (ADC)/FAA Joint-Use

- 1. In addition to the consideration in Par. 210.2 above, ADC/FAA Long Range Radårs that are to feed military and FAA facilities are subject to joint evaluation as directed in the publication ADC'M 101-1, FAA CA 6430, "Joint ADC/FAA Ground Radar Evaluation Manual." The Joint Evaluation will be the basis for establishing the technical standards to which a facility must be maintained, as well as the basis for daily and quarterly certification as in Par. 301 and 301.2 of this manual.
- 2. The Maintenance Engineer in Charge (EIC) at the FAA Air Route Traffic Control Center will will be responsible for system certification to the ATC Chief of the Center of a joint-use Radar, based on:
- (a) Certification by him of the components of the system that are located at the Center; e.g., remoting equipment termination, video distributors, decoders, display equipments, etc.
- (b) Certification by him of the system (PPI) sensitivity, where applicable, in accordance with SM P 6340.2, Section 3, Paragraph 86.

210.5 Flight Inspection Requirements

- (1) In addition to the flight inspection directed in Par. 210.3 above, there will be periodic operational checks of the radar system performed by FAA Jet and Semi-Automatic Flight Inspection (SAFI) aircraft in conjunction with the FAA air traffic controller. These checks will supplement the performance assurance obtained through daily operational observation of the system. The checks will be made as follows:
- (a) Observation of identified targets under control within the sector and comparing them

Per. 210

763-667 0 - 67 - 3

against data obtained during the commissioning flight inspection or through minimum performance requirements developed at the facility.

- (b) Checking the accuracy of as many of the predetermined checkpoints as possible while SAFI or FAA jet flights are operating within the area of radar coverage.
- (2) Special flight inspections will be accomplished in accordance with Par. 104.4 of the USSFIM. A special flight inspection will be called for under the following conditions:
- (a) When a reported deficiency is not susceptible to exact measurement or to verification by ground measurement.
- (b) After an aircraft accident in which the Radar Facility may have been involved.
- (c) After an antenna change, antenna tilt change, or when engineering judgement indicates a probable change in antenna radiation pattern. On a terminal type radar with a variable tilt antenna and remote tilt indicator, the normal tilt shall be that tilt established during a flight inspection. This type of radar shall be considered as not certified for use in the National Airspace System at any time there is a deviation from this tilt and shall not be utilized by the FAA until normal tilt is restored.
- (d) After a modification or other circumstance that, in the judgement of the Engineer in

Charge, makes it necessary for recertification of facility performance.

(e) After the installation of a new map overlay or video map plate to be used for Air Traffic Control purposes, or when navigational aids or fixes have been added or relocated or are otherwise not coincident with an overlay or map plate previously approved.

210.6 Performance Standards

- (1) The radar system will be maintained to the standards determined and recorded at the time of the commissioning flight inspection. It will be maintained within tolerances specified in the applicable technical order, manuals, and any applicable interagency agreements.
- (2) In addition to the general requirements stated in the preceding paragraph, certification of an equipment or facility shall be based on the measurement of mandatory parameters. These are specified in Tables 210-1, Enroute Radar; 210-2, Terminal Radar; 210-3, Secondary Radar (Beacon); and 210-4, Remoting Equipment. Under each catagory is listed the specific parameters whose measurement is required for certification, followed by a list of specific equipment types, together with the name and/or number of the technical publication that contains the maintenance standards and tolerances.

6000.6 CHG 1 1/9/71

TABLE 210-1-Enroute Radar

1. Required Measurements

Transmitter

- a. Peak Power Output.
- b. RF Pulse Alignment.
- c. Spectrum Analysis.
- d. Pulse Width.
- e. VSWR.
- f. T/R Recovery Time.
- g. Ring Time.

Receiver

- a. MDS with parametric amplifier (if installed). (Check MDS on normal, integrated normal and MTI.)
- b. Noise Figure.
- c. Cancellation Ratio.
- d. Sub-Clutter Visibility.
- e. Parametric Amplifier Gain.
- f. Video Limit Level at Junction Box.

2. Equipment Types and Applicable Technical Documents

Tupo	Technical Document
a. FPS-7, -7A, -7B, -7C and -7D	AF T. O. 31P6-2FPS-7() Series.
b. FPS-8	AF T. O. 31P6-2FPS-8 Series, Section 5.
c. FPS-20A, including the FPS-64, -65, -66	AF T. O. 31P6-2FPS-20 Series, Section 6.
and -67.	
d. FPS-24	
e. FPS-27	AF T. O. 31P6-21FPS-27 Series.
f. FPS-35	AF T. O. 31P6-2FPS-35 Series.
g. FPS-37	NAVSHIPS 94370A (UNCL), Section 6, Vol. 3.
h. GPS-4	AF T. O. 31P6-2GPS-4 Series.
i. ARSR-1D, -E, -F and ARSR-2	FAA Handbook, SM P 6340.2, Chapter 4.

TABLE 210-2-Terminal Radar

1. Required Measurements

- a. Power Output.
 - b. Ring Time.
 - c. Minimum Discernible Signal (normal and MTI).
 - d. Cancellation Ratio.
 - e. Output Pulse Spectrum.

- f. Video Output Level.
- g. Range Accuracy.
- h. Azimuth Accuracy.
- i. Map Accuracy.
- j. T/R Recovery Time.

2. Equipment Type and Applicable Technical Documents

Type	Document
a. AN/CPN-18	AF T. O. 31P5-2CPN-18 Series.
b. AN/FPN-47 (ASR-5)	AF T. O. 31P5-2FPN-47 Series.
c. AN/CPN-4	AF T. O. 31P5-2CPN-4 Series.
d. AN/MPN-11	AF T. O. 31P5-2MPN-11 Series.
e. AN/MPN-13	AF T. O. 31P5-2MPN-11 Series.
f. AN/MPN-14	AF T. O. 31P5-2MPN-14 and -2MPN-11 Series.

Table 210.1

6000.6 CHG 1

Tuna	9/71
g. AN/MPN-15 Document h. AN/MPN-16 AF T. O. 31P5-2MPN-11 Series	:
j. AN/FPN-16 14, and -2MPN-17 Series. k. AN/FPN-28 (MPN-5) AF T. O. 31P5-2FPN-16 Series.	'X-
1. AN/CPN-4A, MPN-11E, MPN-14A, NAVWEPS 16-30 (PN-4-1, -5, -6, -7, -8, and NAVSHIPS 937.42, TM 11-5840-293-35.	42. -9.

TABLE 210-3—Secondary Radar

1. Required Measurements

Transmitter

- a. Pulse width of each pulse.
- b. Pulse spacing of all pulses (each mode).
- c. Power output of each pulse.
- d. Monitor alarm point.
- e. Range error alarm.
- f. Trigger spacing.

Receiver

- a. Sensitivity.
- b. Noise figure.
- c. Video output.
- d. Receiver gain monitor alarm point.

2. Equipment Types and Applicable Technical Documents

Type	couleill?
a. ATCBI-1	Document
b. A1CBI-2	Manufacturers Instruction Book.
· riobi-3	
4. 114/UI 41-8A	A TO THE CONTROL OF THE PARTY O
~ 11M/UFA=9B	AF T. O. 31P4-2GPX-8() -2, Section 5.
1. 214/UPA-6	24 1. U. 31P4-2(†PX-9/ \ -0 @
8. AM/CT-X-14	Ar 1. (), 31P4-211PX-C-9 Coasing a
h. AN/UPX-1 i. AN/UPX-1A	Ar 1. O. 31P4-2UPX-14-9. Chapter &
i. AN/UPX-1A	NA (SUILS A1343)
j. AN/GPX-30	NAVSHIPS 91765.
k. AN/GPX-34	NAVSHIPS 93578.
I. AN/GPX-35	NAVSHIPS 93885.
m. AN/TPX-41	NAVSHIPS 94177.
	TM 11-1193.

TABLE 210-4-Remoting Equipment

_	
a. AN/FST-2	AF T. O. 21C1 and Document
D. K.III = 1 = 0 9 and 4	AF T. O. 31S1-2FST-2-2, Section 5, Paragraphs 5-3, 5-24.
b. RML-1, -2, -3 and -4	FAA Handbook, SM P 6350.1, Chapter 4. NAVSHIPS 93515—Motorola Handbook of in-
d () A 0090 /73737 an a	THE 11 EQUAL COO 10 PROPERTY.
	36-1. NAVWEPS 1630-FPN-

Table 219.2

221 Enroute and Terminal Area Communications Facilities

221. Description

Enroute and terminal area communications are provided by various types of air/ground facilities such as air route traffic control centers (ARTCC), flight service stations (FSS), control towers, etc. The facilities consist of air/ground transmitter and receiving equipment, recording equipment, and the necessary control equipment.

221.2 Tabulation of Standards and Tolerances

All communications equipment must meet the standards and tolerances outlined in the applicable T.O.; instruction book; or FAA handbook. The following is a list of equipment parameters which shall be measured:

221.21 Transmitter and Associated Antenna

- (1) Power output at transmitter.
- (2) Power input at antenna.
- (3) Audio frequency response.
- (4) VSWR at transmitter.
- (5) VSWR at antenna.
- (6) Modulation percentage.
- (7) Audio limiting action.
- (8) Output frequency.
- (9) Inter-modulation and cross-modulation between transmitters capable of simultaneous operation.
- (10) Audio distortion.

221.22 Receiver and Associated Antenna

- (1) Sensitivity vs. output level.
- (2) Signal-to-noise ratio.
- (3) Squelch action.
- (4) AVC threshold.
- (5) AVC regulation of audio level.
- (6) Power output capability.
- (7) Selectivity (at 6 dB and 60 dB points).
- (8) Nonsymmetry (at 6 dB and 60 dB points).
- (9) Receiving frequency.
- (10) Audio frequency response.
- (11) Audio distortion.
- (12) Insulation resistance of antenna system.
- (13) Continuity of antenna system.

221.23 Recorders and Reproducers

- (1) Frequency response.
- (2) Signal-to-noise ratio.
- (3) Crosstalk.
- (4) Mechanical tolerances, if appropriate.
- (5) Bias oscillator level, if appropriate.
- (6) Amplifier gain.
- (7) Audio quality.
- (8) Automatic changeover, if appropriate.

221.24 Audio and Switching System

- (1) Gain of each amplifier.
- (2) Frequency response of each amplifier.
- (3) Signal-to-noise ratio of each amplifier.
- (4) Amplifier limiting action, if appropriate.
- (5) Audio level at input and output of each amplifier in the system and as such other points that are appropriate.
- (6) Interchannel crosstalk.
- (7) Noise level of each channel.

221.3 Applicable technical documents

Equipment Technical Document

(1) Transmitters..... Appropriate T.O.; equipment instruction book; or FAA Handbook SM P 6500.2, Chapter 4.

(2) Antennas and
Transmission Lines
(Receiving and
Transmitting).

Appropriate T.O.; equipment instruction book; or FAA Handbook SM P 6506.8, Chapter 4.

(3) Receivers....... Appropriate T.O.; equipment instruction book; or FAA Handbook SM P 6500.7,

(4) Recorders and Reproducers. Chapter 4.

Appropriate T.O.; equipment instruction book; or FAA Handbook 8M P 6500.3.

(5) Audio and Switching Systems.

Chapter 4.

Appropriate T.O.; equipment instruction book; or FAA Handbook 6500.4,
Chapter 4.

221.4 Flight Inspection Requirements

221.41 All maintenance procedures of the communications facility can be accomplished and the facility returned to unrestricted operation without recourse to a flight inspection.

Per. 221

4000.4 April 1947

Page 31 land 32

222 Direction Finding Stations (DF)

222.1 Description

Direction finding stations using standard communications from aircraft, provide bearing information to ground personnel which can be relayed to an aircraft upon request from the pilot. DF Stations operate in the HF. VHF, and UHF range.

222.2 Tabulation of Standards and Tolerances

(1) Bearing Accuracy As established by Ground Inspecsurey.

tion.

222.3 Flight Inspection Requirements

222.31 A flight inspection will be required for any of the following reasons:

(1) When the DF Antenna is replaced.

(2) If a report is received from a pilot or from
 AT personnel that a facility has errors exceeding
 ± 10 degrees and the report is verified by a bearing

Initial Tolerance/Limits ±4° of value established following commissioning flight inspection.

Operating Tolerance/Limits ±4° of value established following last flight inspection.

check of another aircraft in the same vicinity. A confirming flight inspection is required, even though the error cannot be verified by ground or equipment checks.

(3) When a facility is recommissioned following an extended interruption, modernization, or replacement of any bearing determining component.

300 Facility Ground Inspection and Notice to Airmen Procedures

300.1 Introduction

All military air traffic control and navigational aid facilities which have been designated for use in the National Airspace System, shall be ground inspected in accordance with Section 301 and certified by the cognizant authority as meeting the applicable technical performance standards and tolerances established by this manual. Those facilities not meeting the prescribed standards and tolerances as determined by flight inspection and/or ground inspection will be the subject of a Notice to Airmen in accordance with paragraph 302.

301 Facility Ground Inspection, Certification and Recertification Procedures

Facility ground inspection consists of the collecting and recording of appropriate performance data, inspection of facility physical conditions, and a review of the quality of maintenance procedures to determine that the facility is operating within performance tolerances and can therefore reasonably be expected to continue to function properly. The cognizant maintenance authority will be responsible for conducting the ground inspection and assuring that the facility meets the performance standards and tolerances described herein. Based upon this assurance, the cognizant Military authority will forward to the appropriate FAA air traffic operational authority a formal certificate essentially the same as that shown in paragraph 402. Recertification is based on similar ground inspection procedures; however, a formal certificate is not required to be sent the FAA air traffic operational authority. Recertification shall be accomplished in accordance with the ground recertification intervals of paragraph 301.1 and at such times that a facility is restored to a satisfactory operational condition after having been advertised in accordance with paragraph 802.

301.1 Ground Recertification Interval

Facility

Recertification shall be performed at intervals specified in the following table:

Ground Certification Interral

VOR/TVOR	Four-month intervals.
11.8	Two-month intervals.
TACAN	Four-month intervals.
L/MFR	Semiannually.
NDB	Do.
Marker Beacons,	Do.
75 MHz.	
Enroute and	Do.
Terminal Area	
Communications.	
DF	Four-month intervals.
Enroute Redar	Do,
Terminal Radar	Two-month intervals.
Secondary Radar -	Four-month intervals.
Any Facility	Immediately after an air-
	craft accident in which
	the facility may have
	been involved.

301.2 Additional Requirements

Facilities should be visited frequently enough to ensure accurate and reliable operation in accordance with the criteria established in this manual. Each time a facility is visited, the maintenance technician responsible for the facility shall verify facility performance on the basis of one or more of the following criteria:

- (1) Visual and Aural (every visit). Verify by visual and aural observation that equipment is operating normally. This requirement includes, but is not limited to, observations noting meter readings, pilot light indications, extraneous noises, excessive heat, etc.
- (2) Monitoring (scheduled visits and as required). Verify by noting local monitoring information and determining from this information that facility operation is satisfactory. Verification may include a control line check.

determine that control and remote monitor functions are satisfactory.

- (3) Meter Readings (scheduled visits if applicable). Record meter readings and compare with those previously recorded on station records.
- (4) Determine (on scheduled visits, and as required) that facility meets the performance standards and tolerances established in this manual.
- (5) System Ground Check (scheduled visits and as required). Perform ground check and compare results with reference ground check error curve (VOR) and/or with data obtained at the time of the last previous flight inspection. Evaluate this data and determine that facility performance has not departed appreciably (beyond tolerance) from previous system ground check recordings.
- (6) Flight Inspection (scheduled or requested). On the basis of flight inspection evaluation, determine that facility performance is satisfactory. Ground check data shall be recorded immediately following any flight inspection.

* 302 Notice to Airmen Procedures

When it has been determined, either by flight inspection or ground inspection, that a facility

does not meet prescribed technical performance standards or tolerances, the cognizant maintenance technician shall notify the Air Traffic Control Officer having operational jurisdiction over the facility and provide appropriate web-nical information on which to base a Notice to Airmen. In addition to any Military Notice to Airmen action, the appropriate FAA authority shall be notified and will issue any Civil Notice to Airmen required.

Notices to Airmen related to Air Defense Radar Systems are subject to classification restrictions and shall be prepared in accordance with joint ADC/FAA Ground Rules Memorandum of Agreement and Agency Handbook OA P 1600.2, Chapter 16, Paragraph 7. Mutually agreed upon Notice to Airmen phraseology for Air Defense Radars will be incorporated in the local agreement.

Scheduled maintenance shutdowns of military facilities which have been certificated for use in the National Airspace System will be submitted to the appropriate Air Route Traffic Control Center (ARTCC) for concurrence in sufficient time to allow for Notice to Airmen issuance at * least five hours prior to the shutdown.

6000.6 Nadi 1947

400 APPENDIX

401 Glossary and Definitions

- 1. National Aircpace System. The common system of air navigation and air traffic control encompassing communication facilities, air navigation facilities, airways, controlled airspace, special use airspace and associated flight procedures authorized by Federal Aviation Regulations for domestic and international aviation.
- 2. Air Navigation Facility. Any facility used in, available for use in, or designated for use in the aid of air navigation, including landing areas, lights, any apparatus or equipment for disseminating weather information for signaling, for radio-directional finding, or for radio or electrical communication, and any other structure or mechanism having a similar purpose for guiding or controlling flight in the air or for the landing and takeoff of aircraft.
- 3. Air Traffic Control Facility. A facility providing air traffic control service.
- 4. Ground Inspection. The act of technically evaluating an Air Navigation Facility, by competent technical personnel, using appropriate test equipment, in order to determine if facility meets applicable performance standards as outlined in Section 200 of this manual.
- 5. Certification. The act performed by the cognizant military authority in giving a formal certificate to the appropriate FAA air traffic operational authority to affirm that an air navigation facility meets applicable performance standards as outlined in Section 200 of this Manual.
- 6. Recertification. The act performed by the cognizant military authority in locally recording an affirmation that an air navigation facility meets applicable performance standards as outlined in Section 200 of this Manual.
- 7. Formal Certificate. A written statement, based on the satisfactory completion of the initial

- air navigation facility ground inspection, giving formal notice to the appropriate FAA air traffic operational authority that a facility meet applicable performance standards as outlined in Section 200 of this Manual and agreeing to issue a Notice to Airmen should the facility subsequently fail to meet applicable ground or flight inspection criteria. See Appendix 402 of this Manual for the formal certificate form.
- S. Ground Check. A method of verifying from the ground that a facility is radiating accurate information.
- 9. Notice to Airmen. A notice identified either as a NOTAM or Airmen Advisory containing information concerning the establishment, condition, or change in any component of, or hazard in, the National Airspace System, the timely knowledge of which is essential to personnel concerned with flig..t operations.
- a. NOTAM. A notice to Airmen in message form requiring expeditions and wide dissemination by telecommunications means.
- b. Airmen Advisory. A notice to Airmen normally only given local dissemination during preflight or inflight briefing, or otherwise during communication with pilots.
 - 10. VOR. VHF Omnidirectional Radio Range.
 - 11. TVOK. Terminal VOR.
 - 12. /LS. Instrument Landing System.
 - 13. TACAN. Tactical Air Navigation System.
- 14. L/MFR. Low/Medium Frequency Radio Range.
- 15. NDB. Non-Directional Beacon.
- 16. FM, LFM, Z Markers, ILS Marker. 75 MHz marker beacons.
 - 17. DF. Direction Finding Equipment.

Per. 40

400 Appendix Page 2

6000.6 CHG 1 1/9/71

402 Formal Certificate Form

The following certificate shall be completed at the time of initial certification when the facility is accepted for use in the National Airspace

System and forwarded to the proper Federal Aviation Administration official:

CERTIFICATE

The undersigned hereby attests that (name of facility) meets applicable performance standards and tolerances contained in the United States Interagency Ground Inspection Manual and agrees to immediately issue a Notice to Airmen through (name of FAA facility) should the facility subsequently fail to meet applicable ground or flight inspection criteria. In the latter event, it is understood that continued military use of the facility for IFR operations will be disapproved by the Federal Aviation Administration if conflict with other IFR traffic could result.

Signat	ure:
Title:	
Date:	

Per. 402

U. S. GOVERNMENT PRINTING OFFICE - 1971 () - 417-785

OO Appendix

6000.6 CHG 2 January 1973

403 FAA Regional Offices and Addresses

632 Sixth Avenue Alaskan Region -----Anchorage, Alaska 99501 601 East 12th Street Central Region _____ Kansas City, Mo. 64106 John F. Kennedy International Airport Eastern Region -----Federal Building Jamaica, N.Y. 11430 Amembassy-FAA Europe-Africa-Middle East ----Tour-Madou Building 1 Place Madou, Brussels 3, Belgium APO New York 09667 2300 East Devon Avenue Great Lakes Region -----Des Plaines, Ill. 60018 154 Middlesex Street New England Region -----Burlington, Mass. 01803 Boeing Field Northwest Region -----Seattle, Wash, 98108 Post Office Box 4009 Pacific Region _____ Honolulu, Hawaii 96812 Post Office Box 20636 Southern Region -----Atlanta, Ga. 30320 Post Office Box 1689 Southwest Region _____ Fort Worth, Tex. 76101 Post Office Box 7213, Park Hill Station Rocky Mountain Region -----Denver, Colo. 80207 5651 West Manchester Avenue Western Region -----Post Office Box 90007, Airport Station Los Angeles, Calif. 90009

Per. 40: